






Single Axis Tracking System Installation Notes

POA DENO SENSOR – If provided, use the location plan. If not, try to locate in most representative Plane-of-Array for the system. Sensor must be 3 rows in from perimeter with good line of sight to the gateway antenna

- Mount to north edge of panel as close to center of the torque as possible at motor using included clamps
- AVOID: Shade or obstructions, the Perimeter of the Array, and mounting too close to an inverter
- Sensors are shipped perfectly square & level to bracket. Use set screws on bottom of Deno Sensor to fine tune alignment to ensure a perfect POA.

rPOA (if applicable) – rear-side pyranometer – Mount to bottom of torque tube. Must be 3 modules in from end of row (**IMPORTANT:** separate Dual lock pieces, clean mounting surface, mount first piece of dual lock, mate rPOA sensor)

Tbom – Temp Back of Mod – Mount to back of module. Must be at least 1 module in from end of row. (**IMPORTANT:** separate Dual lock pieces, clean mounting surface, mount first piece of dual lock, mate Tbom sensor)

Antennas (Dual)

- Mount an antenna on either side of the module in the first module gap using supplied hardware and connecting to Deno Sensor coaxial cable Y-connector



Denowatts

Title: **DENO SENSOR (D4) TRACKER MOUNT INSTALLATION**

Issued: November 2025

Installation Cut Sheet

Sheet: 3 of 3